

## 台北市北投區清江國民小學 4 月份 飲水機維護紀錄表

編號	位置	樓層	機型	濾芯規格	濾芯更換	機台巡檢	功能操作	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	出廠年月	備註
1	七星樓(總務處外)	1F	賀眾UW-10000A	61.64		✓	✓	✓	✓	✓	✓	✓	2016	
2	七星樓302外	2F	賀眾UW-20000A	61.64		✓	✓	✓	✓	✓	✓	✓	2017	
3	七星樓402外	3F	賀眾UW-10000A	61.64		✓	✓	✓	✓	✓	✓	✓	2016	
4	丹鳳樓203外	2F	UW-9203	61.64		✓	✓	✓		✓	✓	✓		
5	觀音3樓	1F	賀眾UW-20000A	61.64		✓	✓	✓		✓	✓	✓		
6	丹鳳1F	1F	豪星HM-3188	18.29										故障
7	觀音2F	2F	UW-9203	61.64		✓	✓	✓		✓	✓	✓		
8	觀音4F	4F	UW-9203	61.64		✓	✓	✓		✓	✓	✓		
9	觀音2F	2F	力霸CH-705A	18.29		✓	✓	✓		✓	✓	✓		
10	觀音3F	3F	賀眾UW-20000A	61.64		✓	✓	✓	✓	✓	✓	✓	2017	
11	觀音4F	4F	賀眾UW-20000A	61.64		✓	✓	✓	✓	✓	✓	✓	2017	
12	陽明2F	2F	UW-313	61.64		✓	✓	✓		✓	✓	✓		
13	陽明3F	3F	賀眾UW-20000A	61.64		✓	✓	✓		✓	✓	✓		
14	丹鳳樓102外	1F	賀眾UW-313	UF-11		✓	✓	✓		✓	✓	✓		
15	丹鳳樓203外	2F	賀眾UW-20000A	61.64		✓	✓	✓		✓	✓	✓		
16	丹鳳樓3F	3F	賀眾UW-313	UF-11		✓	✓	✓		✓	✓	✓		
17	幼兒園企鵝班	1F	UW-992	UF-11		✓	✓	✓		✓	✓	✓		
18	幼兒園辦公室	2F	賀眾UW-313	UF-11		✓	✓	✓		✓	✓	✓		
19	游泳池	1F	UW-992	UF-11		✓	✓	✓		✓	✓	✓		
20	活動中心2F	2F	UW-992	UF-11		✓	✓	✓		✓	✓	✓		
21	後穿堂	1F	豪星HM-3188	18.29		✓	✓	✓		✓	✓	✓		
22	後穿堂	1F	豪星HM-3188	18.29		✓	✓	✓		✓	✓	✓		
23	後穿堂	1F	豪星HM-3188	18.29		✓	✓	✓		✓	✓	✓		
24	陽明4樓	4F	豪星HM-3188	18.29		✓	✓	✓		✓	✓	✓		
25	七星2F302外	2F	豪星HM-3188	18.29		✓	✓	✓		✓	✓	✓		
26	丹鳳4F	4F	賀眾UW-10000A	61.64		✓	✓	✓	✓	✓	✓	✓	2017	

日期: 107年4月30日

濾芯更換數量: 0 支 / 機台巡檢數量: 26 台

服務單位  
賀眾牌

服務人員簽章  
張尚新

客戶簽章  
李國裕 4/30